

15540 Woodinville-Redmond Rd NE Building A, Suite 800 Woodinville, WA 98072

FREEFLYSYSTEMS.COM

Date Released: October 21, 2015 Date Effective: October 21, 2015 Subject: Motion Booting Default

Effectivity: All ALTAs

Require Action: Verify Motion Booting parameter

Time of Compliance: Prior to flight

BACKGROUND

It was recently discovered that through the process of upgrading Synapse firmware from 3.02 to 3.4, the Motion Booting parameter can be set to ON. This update was occurring in the factory for certain ALTAs shipped with Synapse firmware 3.02 causing the Motion Booting parameter to be set to ON when shipped. Freefly recommends that this is setting be turned off under normal conditions since it bypasses error checking processes.

This Service Bulletin is being issued only to potentially affected ALTA operators.

RECOMMENDATIONS

Freefly recommends that affected operators verify that the Motion Booting parameter is set to the appropriate setting (typically OFF) prior to next flight.

For Service Information Contact: Freefly Customer Support

Email: support@freeflysystems.com

Phone: +1 (425) 485-5500

Hours of Operation: M-F 8am-6pm PST